

FIG. 2

2 / 15

MACHINE CONFIGURATION				COMPONENT TRANS- FORMATION MATRIX M_a	AXIS TRANS- FORMATION MATRIX M_c	ANGLE ADDITION VALUE Δ
FIRST ROTATION AXIS	SECOND ROTATION AXIS	TOOL AXIS	MASTER AXIS			
A	C	Z	NOT DESIGNATED	$\begin{bmatrix} 0 & 0 & 1 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & -1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\begin{bmatrix} 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	0
			NOT DESIGNATED	$\begin{bmatrix} 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\begin{bmatrix} 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	0
B	C	Z	NOT DESIGNATED	$\begin{bmatrix} 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\begin{bmatrix} 1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	0
			NOT DESIGNATED	$\begin{bmatrix} 0 & 0 & 0 & 0 \\ 0 & 0 & -1 & 0 \\ 0 & 0 & 0 & 1 \\ 0 & 0 & 0 & 0 \end{bmatrix}$	$\begin{bmatrix} 1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	0
B	A	X	B	$\begin{bmatrix} 0 & 1 & 0 & 0 \\ -1 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\begin{bmatrix} 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\frac{\pi}{2}$
			A	$\begin{bmatrix} -1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & -1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\begin{bmatrix} 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$	$\frac{\pi}{2}$


FIG. 3


FIG. 4

FIG. 5




FIG. 6




FIG. 7






FIG. 9




FILET INSERTION IN EXPRESSION BY CONVERSION
INTO ROTARY COORDINATE SYSTEM

FIG. 8



JUDGMENT TO BE
BENT IS DIFFICULT

(A) EXPRESSION BY SPHERICAL COORDINATE



(B) EXPRESSION BY ROTARY COORDINATE SYSTEM

FIG. 10








FIG. 11**FIG. 12**


FIG. 13




BEHAVIOR OF LINEAR COORDINATE AXES IN MACHINE COORDINATES



A-AXIS




B-AXIS




FEED RATE

BEHAVIOR OF ROTARY AXES
IN MACHINE COORDINATES



A-AXIS



B-AXIS

BEHAVIOR OF ROTARY AXES
IMPROVED IN RAPID CHANGE

FIG. 14




FIG. 15a




FIG. 15b




FIG. 15c




FIG. 16a




FIG. 16b




FIG. 16c




FIG. 17a




FIG. 17b




FIG. 17c

